


2025.03.21



2025.03.21

2025.03.21



46,75883, 14,37739, 528,6m, 273°
21.03.2025 08:34:57

[link](#)



46,75881, 14,37737, 528,5m, 111°
21.03.2025 08:34:36

[link](#)

2025.03.21



46,75875, 14,3774, 531,6m, 290°
21.03.2025 08:34:10

[link](#)

[link](#)

Schachterhebungsprotokoll

SchachtNr: 286

Schachttiefe: 2,78 [m]

Deckel DN: 68 [cm]

Rund Eckig

Verschraubt: ja nein

Material: Grauguss-beton

Klasse: D 400 [Kn] [I]

Belüftet: ja nein

Schmutzfänger: ja nein

Schacht DN: 80x60 [cm]

Rund Eckig

Gallmayer

Inspekteur: _____ Datum _____


Funktion: Strang, HA, EL


DN: 000 [mm]

Material: beton

Tiefe: 2,78 [m]

Ablauf





46,75883, 14,37714, 530,8m, 246°

21.03.2025 08:39:19

WM24