


2025.03.12



2025.03.12



46,75857, 14,37636, 536,2m, 16°
12.03.2025 08:41:50

[link](#)

2025.03.12



46,75851, 14,37632, 535,7m, 15°
12.03.2025 08:41:27

[link](#)

[link](#)

Schachterhebungsprotokoll



SchachtNr: 323
Einlaufschacht

Inspekteur: _____ Datum: 12.3.25

Ablauf

Funktion: Strang, HA, EL

Schachtiefe: _____ [m]
Deckel DN: 66 [cm]
Rund Eckig

DN 200 [mm]

Material PVC

Tiefe: 0,75 [m]



Verschraubt: ja nein

Material: Grauguss
Klasse: C 250 [kn] [t]

Belüftet: ja nein

Schmutzfänger: ja nein

Schacht DN: 0,80 [cm]
Rund Eckig



46,75822, 14,37654, 519,3m, 173°
12.03.2025 12:53:50