

2025.03.20



2025.03.20



46,75765, 14,3787, 536,6m, 20°  
20.03.2025 08:47:33

[link](#)

2025.03.20



46,75766, 14,37869, 536,6m, 172°  
20.03.2025 08:47:11

[link](#)

[link](#)

**Schachterhebungsprotokoll**

SchachtNr: 488

Schachttiefe: 1,10 [m]

Deckel DN: 68 [cm]

Rund  Eckig

Verschraubt: ja  nein

Material: Grauguss

Klasse: D 400 [kn] [t]

Belüftet: ja  nein

Schmutzfänger: ja  nein

Schacht DN: 100 [cm]

Rund  Eckig

Inspekteur: \_\_\_\_\_ Datum \_\_\_\_\_

Funktion: Strang HA, EL

DN 150 [mm]


Material PVC

Tiefe: 1,10 [m]

**Ablauf**



DN 150  
PVC  
0,53m



46,75764, 14,37874, 515,3m, 339°

20.03.2025 08:49:33